INVOICE

FROM

Foothill Gear Auto Repair

2630 Fruitridge Road
Sacramento, CA 95820
service@foothillgear.example
+1 916 555 0172

BILL TO

Teresa Montoya
418 Cypress Court
Sacramento, CA 95822
t.montoya@mail.example

Invoice no. **FGA-00007**
Issued **2 Mar 2026**
Due **16 Mar 2026**

WORK PERFORMED	QTY	UNIT	RATE	AMOUNT
Labour				
Diagnosis: brake and charging tests, no charge	1	job	$0.00	$0.00
Replace front brake pads and rotors, road test	1.6	hrs	$160.00	$256.00
Replace alternator, inspect drive belt	1.8	hrs	$160.00	$288.00
Labour subtotal	**3.4**	**hrs**		**$544.00**
Parts				
Ceramic pad set, part no. BP-1089 (new)	1	set	$64.95	$64.95
Brake rotor, part no. RT-31244 (new)	2	ea	$82.50	$165.00
Alternator, part no. AL-11592 (remanufactured)	1	ea	$238.00	$238.00
Alternator core charge, credited on core return	1	ea	$60.00	$60.00
DOT 3 brake fluid	1	qt	$9.25	$9.25
Parts subtotal				**$537.20**
Total hours	**3.4**	**hrs**		

PAYMENT DETAILS

Foothill Gear Auto Repair
Account 0123456789
Example Bank

Subtotal $1,081.20

TOTAL DUE **$1,081.20**

NOTES

ARD 000000, EPA ID CAL000000000 (sample numbers). Warranty 12 months / 12,000 miles. Sales tax not shown in this invented example.

TERMS

Estimate $1,050.00 signed 2 Mar 2026, 08:15; +$31.20 (parts, fluid) approved by phone, T. Montoya, 2 Mar, 11:20, 916-555-0141. Brake parts returned; alternator kept for core.

Customer acceptance